

TECHNICALDATASHEET

CERAMI-TECH E.G.



Two Component Ceramic Epoxy Repair Compound

Thortex Cerami-Tech E.G. is a high performance multi purpose metal repair compound specifically developed for rebuilding metal components in a fluid flow environment damaged by erosion and corrosion.

Thortex Cerami-Tech E.G. uses a complex blend of epoxy resins and a polyamino-amide curing system reinforced with carbide and ceramic particles to produce a coating with a high level of abrasion and erosion resistance combined with optimum physical and mechanical strength.

Thortex Cerami-Tech E.G. can be applied to any damaged component in one easy application and is ideal for rebuilding pump bodies, impellers, propellers, guide vanes, valves, tube sheets, water boxes, rudders, heat exchangers etc.

Before proceeding, please read the following information carefully to ensure that the correct application procedure is fully understood.

SURFACE PREPARATION

All dust and loose material should be scraped away. Oil and grease should be removed with **Thortex Universal Cleaner**. Surfaces should then be abrasive blast cleaned to a minimum Sa2¹/₂ BS7079 Part A1 : 1989 or equivalent with a blast profile of 75 microns (3 mil) corresponding to 'Medium' in BS7079 Part C3/ISO 8503/1. All loose abrasive dust and debris must be blown clear or vacuum cleaned away.

Equipment that has been salt impregnated due to service conditions should first be wet blasted then dry abrasive blasted and checked for presence of salts, this process should be repeated until the salts are removed.

Alternatively, surfaces should be warmed with a blow torch or similar to bring salts up to the surface. The surface should once again be blast cleaned. This procedure must be repeated until no further sweating of impregnated salt is evident. On sections of repair which are not required to bond to the **Thortex Cerami-Tech E.G.** these surfaces should be treated with **Thortex Release Agent**.

MIXING

Thortex Cerami-Tech E.G. is a two component material comprising base and activator components which must be mixed together before use.

Transfer the entire contents of the base and activator containers onto a clean mixing board or other suitable surface. Alternatively measure three volumes of base component and one volume of activator onto a clean mixing surface. The two components should be thoroughly mixed until completely streak free.

The mixed material should be used within 25 minutes of mixing at $20^{\circ}C$ (68°F). This time will be reduced at higher temperatures and extended at lower temperatures.

APPLICATION

Application should not be carried out at temperatures below 5°C nor when relative humidity exceeds 85% or when the surface to be repaired is less than 3°C above the dew point.

The mixed material should be pressed firmly onto the prepared area, care should be taken to avoid air entrapment on deeply pitted surfaces. Application should be carried out as soon as possible after surface preparation is complete, and certainly the same day, otherwise flash blasting will be necessary before application.

Where necessary **Thortex Reinforcement Tape** should be stippled into the mixed product and further material applied over

TX13/0507

In areas where a second layer of Thortex Cerami-Tech E.G is required, this application must be carried out within the initial set time for the first layer, if this is not possible surfaces will require thorough abrasion or abrasive blasting prior to any subsequent material being applied.	Food Contact Meets USDA requirements for incidental food contact. Meets FDA requirements CFR 21.175.300 for food contact. Canadian Food Inspection Agency - Accepted product	
Machining of Thortex Cerami-Tech E.G will cause excessive tool wear so care should be taken to finish the repair to the required size or dimensions. Formers treated with Thortex Release Agent can be used to minimise machining.	PHYSICAL PROPERTIES	
Once the Thortex Cerami-Tech E.G. has reached initial set the material can be separated from surfaces treated with Thortex Release Agent.	Compressive Strength ADTM D695	1055 kg per cm ² (15000psi)
All equipment must be cleaned IMMEDIATELY after use with Thortex Universal Cleaner or equivalent.	Tensile Shear Adhesion ASTMD1002 Flexural Strength ASTMD790	 175 kg per cm² (2500psi) (Grit Blasted Steel) 700 kg per cm² (10000psi)
Volume Capacity 417cc (25.4 cu ins) per kilo	Heat Distortion Temperature ASTM D648 Hardness (Rockwell R) ASTM D785	90°C (194°F) 100
Detailed working recommendations are available from the Technical Centre on request.	Abrasion Resistance ASTM D4060 Nuclear Decontamination BS 4247 Part 1	0.06 ml per 1000 cycles - 1 kg load/CS17 Wheel Excellent
PHYSICAL CONSTANTS	HEALTH AND SAFETY	
Mixing Ratio Base Activator		

By volume

By weight

25 minutes

1 hours

2 hours

5 days

As long as normal good practice is observed **Thortex** Cerami-Tech E.G. can be safely used.

Protective gloves should be worn during use.

A fully detailed **Material Safety Data Sheet** is either included with the material or is available on request.

PACKAGING

Supplied in 2kg packs.

The information provided in this Product Data Sheet is intended as a general guide only and should not be used for specification purposes. The information is given in good faith but we assume no responsibility for the use made of the product or this information because this is outside the control of the company. Users should determine the suitability of the product for their own particular purposes by their own tests.



WWW.thortex.co.uk Thortex Division of E. Wood Ltd. Standard Way, Northallerton, N. Yorks. U.K. DL6 2XA Tel: +44(0)1609 780170 Fax: +44(0)1609 780438 & 777905 E Mail: thortex@ewood.co.uk

FOR FURTHER INFORMATION PLEASE CONTACT

3

5

Base

Activator

Usable Life

Full Mechanical

Initial Set Machining Time

100%

Nil

Appearance

at 20°C (68°F)

Volume Solids

V.O.C.

Shelf Life

Drying & Cure times

1

1

Use within 5 years of purchase. Store in original sealed containers at temperatures between 5°C (40°F) and 30°C (86°F).

Grey Paste

Light Grey Paste